LEITNER ServiceInfo 01/2017

New Service offer and Product information



Non-destructive testing of brake components

To ensure safe operation of the brakes, it is a legal requirement that some components are regularly checked by a non-destructive method.

From this year some of our hydraulic service technicians have the ability to perform non-

destructive testing (MT / VT). Therefor we are able to provide a complete service, including non-destructive testing in the revision of emergency- and service brakes. In a further step, we will expand our capabilities in order to offer an even wider range of non-destructive testing for you. For a quote or further information, please contact your account manager.

Slide bearing bushings for rope grips

In the future, the slide bearing bushings of type Fiberglide (metal bushing with fabric inlay) will be replaced by plastic bushings of type IGUS. This product is already



successfully used for many years and has the advantage that it is cheaper, and in light wear the appropriate bolts are not damaged. You can always contact your responsible person for spare parts to receive an advice.

Attached you will find all material numbers with the corresponding order numbers. Please add this replacement, where appropriate, also in your operating manual.



OUR CUSTOMER SERVICE HOTLINE Available 365 days / 24 hours

Mechanical Service +39 335 6156050 Electrical Service +39 335 6514386 Customer Service

LEITNER ServiceInfo 01/2017

Rope grips LEITNER LA23-LA48-LA612 – Slide bearing NEW

Rope grip LA 23

Material number old	Material number new	
Slide bearing 00033300	Slide bearing 20015615 22/25DX20	
Slide bearing 00033296	Slide bearing 20016112 18/20DX10	
Slide bearing 00048418	Slide bearing 20016126 16/18DX15	

Rope grip LA 48

Material number old	Material number new	
Slide bearing 00033298	Slide bearing 20002815 24/27DX25	
Slide bearing Glacier 44934	24/27DX25	
Slide bearing 00033297	Slide bearing 20016113 18/20DX20	Drilled slide bearing 41059897
Slide bearing Glacier 44933	18/20DX20	Drilled slide bearing 2412571
Slide bearing 00033296	Slide bearing 20016112 18/20DX10	Drilled slide bearing 41058456
Slide bearing Glacier 44932	18/20DX10	Drilled slide bearing 2412570

Rope grip LA 612

Material number old	Material number new	
Slide bearing old 00033301	Slide bearing 20015782 32/36DX40	
Slide bearing Glacier 44609	32/36DX40	
Slide bearing 00033300	Slide bearing 20015615 22/25DX20	Drilled slide bearing 51125769
Slide bearing Glacier 44608	22/25DX20	Drilled slide bearing 2412573
Slide bearing 00033299	Slide bearing 20015614 22/25DX15	Drilled slide bearing 41059899
Slide bearing Glacier 44607	22/25DX15	Drilled slide bearing 2412572



OUR CUSTOMER SERVICE HOTLINE Available 365 days / 24 hours

Mechanical Service +39 335 6156050 Electrical Service +39 335 6514386 Customer Service



Rope grip LPA – Sliding bearing NEW

Rope grip LPA-N

Material number old	Material number new	
Slide bearing 00033298	Slide bearing 20002815 24/27DX25	
Slide bearing 00017479	Slide bearing 20002816 25/28DX25	
Slide bearing 00039461	Slide bearing 20002817 28/32DX25	
Slide bearing 00017381	Slide bearing 20002819 44/48DX20	
Slide bearing 00017479	Slide bearing 51104836 25/28DX25	slit (20002816)

Rope grip LPA-M/L/XL

Material number old	Material number new	
Slide bearing 00033298	Slide bearing 20002815 24/27DX25	
Slide bearing 00017479	Slide bearing 20002816 25/28DX25	
Slide bearing 00017478	Slide bearing 20002818 30/34DX25	
Slide bearing 00017477	Slide bearing 20002820 50/55DX25	
Slide bearing 00017479	Slide bearing 51104836 25/28DX25	slit (20002816)



OUR CUSTOMER SERVICE HOTLINE Available 365 days / 24 hours

Mechanical Service +39 335 6156050 Electrical Service +39 335 6514386 Customer Service